



FORKLIFTS, INC.

Because You'll Speak To An Owner Every Time™

Renting, Selling, & Servicing Forklifts Since 1960

4780 Mendel Ct SW. Atlanta, Georgia 30336
Telephone (404) 696-0566 -Fax (404) 696-0956
www.ogdenforklifts.com

Installation & Care

BATTERY MAINTENANCE MADE SIMPLE!

Battery Maintenance Checklist

- ✔ Never smoke or have open flame or spark near a battery.
- ✔ Always wear personal safety wear when inspecting, servicing or working near batteries.
- ✔ Always maintain correct electrolyte levels as specified.
- ✔ Always maintain batteries in clean and dry condition.
- ✔ Always insure no metal objects come into contact with the battery.
- ✔ Always add distilled or approved water only. If spill-overs occur, contact battery expert for service.
- ✔ Discharge batteries no more than 80% of their rated capacity. Ideal discharge/charge parameters are 6 hours use, 8 hours charge and 4 hours cool-down prior to use.
- ✔ Never place a hot battery on-charge or in operation. If battery is hot (+115F), contact battery expert for inspection.
- ✔ Always perform and record electrolyte and cell voltage readings on a minimum quarterly basis on each 75 discharge cycles.
- ✔ Remove or open all covers from batteries during charge, insure adequate ventilation exists in all areas where batteries are being charged.